



Case study: Mechanical Engineering



ELECTRICAL MECHANICAL PROCESS

Client:

Cumbria water site

Challenge:

We bespoke made a treatment tank for contaminated water on a site in Cumbria. Our client's previous tank was manufactured from mild steel and had degraded due to the acidity of the liquid.

Result:

We used our fabricator to manufacture a HDPE tank, with integrated weir plates and lid, to meet with our customer's exact specification.